

Component List of 3S Air Pin Type Lower Electrode Set for M10

Model No. list

Model No.		① 3S Air Pin For Nut Welding	② Air Cap For Nut Welding	③ Lower Holder For Nut Welding
Square Nut Hexagonal Nut	PNSET-10-10.8-3016-1-K	DPN-10P-10.8-K	PN-C10-11.0-30-C	PN-SH2-1 (T=1/10)
	PNSET-10-10.8-3016-2-K			PN-SH2-2 (T=MT#2)
	PNSET-10-10.8-3016-3-K			PN-SH2-3 (T=1/5)
Hexagon pilot nut	PNSET-P10-12.8-3016-1-K	DPN-10P-12.8-K	PN-C10-13.0-30-C	PN-SH2-1 (T=1/10)
	PNSET-P10-12.8-3016-2-K			PN-SH2-2 (T=MT#2)
	PNSET-P10-12.8-3016-3-K			PN-SH2-3 (T=1/5)

① 3S Air Pin For Nut Welding
Center-Misalignment Prevention, Shouldered Type


② Air Cap For Nut Welding

③ Air & Spring Lower Holder for Nut Welding

Commonn component:
Bakelite Plate
BU-612-8

Commonn component:
Spring
SP-68-24

Commonn component:
Speed Controller B (meter-in)
PSL-601B



[Applicable conditions]
Square Nut / Hexagonal Nut



Workpiece thickness: ~t2.6
Pilot hole: φ11.0

[Applicable conditions]
Hexagon pilot nut



Workpiece thickness: ~t2.6
Pilot hole: φ13.0

Part name	Use Quantity	MOQ
3S Air Pin Type Lower Electrode Set	-	1set
① 3S Air Pin For Nut Welding Center-Misalignment Prevention, Shouldered Type	1	1
② Air Cap For Nut Welding	1	1
③ Air & Spring Lower Holder for Nut Welding	1	1
Commonn component: Speed Controller B (meter-in)	1	1
Commonn component: Bakelite Plate	1	5
Commonn component: Spring	1	5